

MODEL CHART		
Model	Output	Selectable Ranges
MS-121*	4 to 20 mA	0.1 in, 0.25 in, 0.5 in w.c. (25, 50, 100 Pa)
MS-321*	0 to 10 V	0.1 in, 0.25 in, 0.5 in w.c. (25, 50, 100 Pa)
MS-721*	0 to 5 V	0.1 in, 0.25 in, 0.5 in w.c. (25, 50, 100 Pa)
MS-111*	4 to 20 mA	1 in, 2 in, 5 in w.c. (250, 500, 1250 Pa)
MS-311*	0 to 10 V	1 in, 2 in, 5 in w.c. (250, 500, 1250 Pa)
MS-711*	0 to 5 V	1 in, 2 in, 5 in w.c. (250, 500, 1250 Pa)
MS-131	4 to 20 mA	10 in w.c. (2 kPa)
MS-141	4 to 20 mA	15 in w.c. (3 kPa)
MS-151	4 to 20 mA	25 in w.c. (5 kPa)
MS-331	0 to 10 V	10 in w.c. (2 kPa)
MS-341	0 to 10 V	15 in w.c. (3 kPa)
MS-351	0 to 10 V	25 in w.c. (5 kPa)
MS-021	4 to 20 mA	±0.1 in, 0.25 in, 0.5 in w.c. (±25, 50, 100 Pa)
MS-221	0 to 10 V	±0.1 in, 0.25 in, 0.5 in w.c. (±25, 50, 100 Pa)
MS-621	0 to 5 V	±0.1 in, 0.25 in, 0.5 in w.c. (±25, 50, 100 Pa)
*Note: For duct mount static pressure probe, change last digit from		
1 to 2. Example: MS-122		

ACCESSORIES Model Description A-435 Field upgradeable LCD A-480 Plastic static pressure tip A-481 Installer kit. Includes 2 plastic static pressure tips and 7 ft (2.1 m) of PVC tubina A-489 4" straight static pressure tip with flange A-302F-A 303 SS Static Pressure Tip with mounting flange. For 3/16" ID rubber or plastic tubing. 4" insertion depth. Includes mounting screws 100 to 240 VAC/VDC to 24 VDC Power supply SCD-PS

OPTIONS		
To order add suffix:	Description	
-LCD	Units with display	
Example: MS-121-LCD		
-NIST	NIST traceable calibration certificate	
Example: MS-021-NIST		
-FC	Factory calibration certificate	
Example: MS-021-FC		

Process Tubing Options: See page 503 (Gage Tubing Accessories)

Differential Pressure Transmitters